



TROUBLE SHOOTING GUIDE


TSG-2020-0007

| | | | | | | | |
|-------------|------------|-----------------|-------|-----------------|--------|---------------|--------|
| DATE | 28/11/2020 | ISSUE BY | Zaidi | CHECK BY | Rashid | APP.BY | Mazmin |
|-------------|------------|-----------------|-------|-----------------|--------|---------------|--------|

| | | | |
|--------------|--------|----------------|---------------------------|
| MODEL | 135 LC | PROBLEM | Cannot install mirror L/H |
|--------------|--------|----------------|---------------------------|

| | |
|----------------|---|
| SYMPTOM | no thread mirror at handlebar L/H (N/V) |
|----------------|---|

| | | |
|--------------|---|--|
| PHOTO |   | Thread mirror damage at Handlebar |
|--------------|---|--|

| ITEMS | DESCRIPTION | PHOTO | |
|------------------------|-------------|---|---|
| Check Point | Step 1 | Check thread mirror | |
| | Step 2 | Check handlebar bracket mirror L/H | |
| | Step 3 | | |
| | Step 4 | | |
| Problem Finding | Step 1 | Thread damage inside mirror handlebar L/H |  |
| | Step 2 | | |
| Action Taken | Step 1 | Replace the handlebar comp . | |
| | Step 2 | | |
| Test Result | 1 | Problem solved. | |
| | 2 | Tested -ok- | |
| | 3 | | |